


Model NO. 87240 AIROPERATED GREASE PUMP

Series "C"






One Lincoln Way St. Louis, Missouri 63120-1578 (314) 679-4200

Copyright 1996 Printed in U.S.A. Section -M23

Page - 26E



SERVICE PARTS

| Part | Qty. | Description | Part | Qty. | Description |
|--------|------|-----------------------------|----------|------|------------------------------|
| *10061 | 1 | Check disc | 51039 | 1 | Nut |
| 10127 | 1 | Vent plug | 55138 | 4 | Valve seat spring |
| 11470 | 1 | Valve cap | 55231 | 1 | Spring |
| 11471 | 1 | Trip rod collar | 56003 | 1 | Pump check spring |
| *11472 | 1 | Trip rod pin | 56038 | 2 | Equalizer spring |
| *11475 | 1 | Trip shoe | 62633 | 1 | Steel tubing |
| 11904 | 1 | Packing nut | 66002 | 1 | Ball |
| 11905 | 1 | Packing cap | *66010 | 2 | Ball |
| 11947 | 1 | Trip sleeve | 66200 | 2 | Tube connector |
| 12093 | 1 | Check housing | 67044 | 1 | Pipe plug |
| 12094 | 1 | Air piston bolt | 68797 | 1 | Plug Button |
| 12095 | 1 | Outlet body | 68849 | 1 | Strainer |
| 12096 | 1 | Outlet block | 68850 | 1 | Filler cap |
| 12511 | 1 | Pipe plug | *83063 | 1 | Valve slide, seat, & gasket |
| 12834 | 1 | Spring retainer | 84508 | 1 | Plunger, bushing & 0-ring |
| 14449 | 1 | Tie rod | 84509 | 1 | Pump assembly |
| 16577 | 1 | Connector | 87849-14 | 1 | Rupture assembly |
| 30011 | 1 | Valve cap gasket | *90770 | 1 | Trip rod |
| *31007 | 2 | Gasket | *91331 | 1 | Toggle plate |
| 31047 | 1 | Gasket | 91979 | 1 | Reservoir cap |
| 31054 | 1 | Gasket | 93438 | 1 | Bushing and plunger assembly |
| 31056 | 1 | Gasket | 236286 | 1 | Cover |
| 33014 | 1 | Air cylinder gasket | 236615 | 1 | Muffler cover |
| 33039 | 1 | Gasket | *236616 | 1 | Gasket |
| 34090 | 1 | Air piston packing (Buna-N) | 236833 | 1 | Muffler |
| *34110 | 1 | Plunger packing (Buna-N) | *236835 | 1 | Packing |
| *34158 | 1 | Cover gasket (Neoprene) | 236868 | 4 | Screw |
| 34165 | 1 | 0-ring (Buna-N) | 236869 | 6 | Screw |
| 34308 | 1 | Gasket (Buna-N) | 236870 | 4 | Valve seat bolt |
| 34314 | 1 | O-ring (Buna-N) | 237562 | 1 | Air valve casting |
| *38162 | 1 | Valve seat gasket (Buna—N) | *244313 | 1 | Seat |
| 40821 | 1 | Base casting | *244359 | 1 | O-ring (Buna-N) |
| *45605 | 1 | Valve guide plate | *245425 | 1 | Trip rod packing nut |
| 48212 | 2 | Air piston washer | 246816 | 1 | Packing nut gasket o |
| 48237 | 1 | Plunger packing washer | 247244 | 1 | Reservoir (Acrylic) 🏻 |
| 50000 | 6 | Screw | 247456 | _ | Disc (pink) (Pkg of 10) @ |
| 50521 | 4 | Screw | 360383 | 1 | Base |

^{*} Recommended service parts inventory

© Indicates Change

TROUBLESHOOTING

| Problem | Solution | | |
|--|---|--|--|
| Pump operates continuously. | Pump has lost prime — Check lubricant supply. Refill reservoir if necessary. Air pocket trapped in lubricant. Loosen vent plug one turn. Allow pump to operate until trapped air is pumped out. Close vent plug. | | |
| Pump continues to operate without discharging lubricant. | Outlet checks 10061 and 66002 may be fouled — Remove and clean checks and check seats. | | |
| Pump fails to operate. | Check air supply. | | |

- RETAINTHISINFORMATION FOR FUTURE REFERENCE -

When ordering replacement parts, list: Part Number, Description, Model Number and Series Letter. LINCOLN provides a Distributor Network that stocks equipment and replacement parts.