LUBRICATOR

R.H. INTERNAL REAR ROTARY 60:1 RATIO - 2 QUART RESERVOIR INCLUDES BUNA-N OIL SEALS





880187

Model 800219 SERIES

Series "B"

34622 included with pumps, slot covers and filler.





880130

SERVICE PARTS

PART	QUAN.	DESCRIPTION
32077 34622 66652 67007 69944 360659 880019 880085	1 As req'd 1 2 1 1 1 1	Cover gasket Gasket Key Drain plug Strainer Cover plate Gauge glass assembly Filler assembly
880093 880130 880187	As req'd 2 As req'd	Slot cover assembly Bracket assembly Model "55" pump assembly


DRIVE ADAPTATION: Refer to Section M3 Page 42 Series.


LINCOLN ST. LOUIS 4010 GOODFELLOW BLVD · ST LOUIS, MO. 63120 · (314) 383-5900



SECTION -M2

PAGE - 181A





- RETAIN THIS INFORMATION FOR FUTURE REFERENCE

When ordering replacement parts, list: Part Number, Description, Model Number, and Series Letter. LINCOLN ST. LOUIS provides a Distributor Network that stocks equipment and replacement parts.