


Model No. 1823 $CENTRO-MATIC_{\odot}$ DRUM PUMP


AIR OPERATED - 120 LB. DRUM SIZE HIGH PRESSURE 2,500 PSI SYSTEM




LINCOLN INDUSTRIAL

One Lincoln Way St. Louis, Missouri 63120-1578 (314) 679-4200 Copyright 1997 Printed in U.S.A. Section - C8

Page - 27L





The lubrigun will not build up sufficient pressure if the outlet check is fouled. Foreign material may lodge beneath 66001 Ball Check or between 80206 Check Disc and the check seat of the 90204 Outlet Check Bushing.

Sealing surface of disc and seat must form a perfect seal.

Replace if pitted, worn or scored.

83948 VENT VALVE ASSEMBLY

—— RETAINTHISINFORMATION FOR FUTURE REFERENCE ——	_
When ordering replacement parts, list: Part Number, Description, Model Number and Series Letter. LINCOLN provides a Distributor Network that stocks equipment and replacement parts.	
Form	-