

LUBRICATOR
 L.H. INTERNAL REAR ROTARY DRIVE
 60:1 RATIO - 2 QUART RESERVOIR
 INCLUDES BUNA-N OIL SEALS




Model 800505 SERIES

Series "B"

34622 included with pumps,
 slot covers and filler.

880187
 Refer to Section M1
 Page 1 Series.



DRIVE ADAPTATION:
 Refer to Section M3
 Page 43 Series.



SERVICE PARTS

PART	QUAN.	DESCRIPTION
32077	1	Cover gasket
34622	As req'd	Gasket
67007	2	Drain plug
69944	1	Strainer
69973	1	#5 Woodruff key
360659	1	Cover plate
880019	1	Gauge glass assembly
880085	1	Filler assembly
880093	As req'd	Slot cover assembly
880130	2	Bracket assembly
880187	As req'd	Model "55" pump assembly

LINCOLN ST. LOUIS
 4010 GOODFELLOW BLVD • ST LOUIS, MO 63120 • (314) 383-5900



SECTION - M2
PAGE - 182A



RETAIN THIS INFORMATION FOR FUTURE REFERENCE

When ordering replacement parts, list: Part Number, Description, Model Number, and Series Letter.
LINCOLN ST. LOUIS provides a Distributor Network that stocks equipment and replacement parts.