


**LUBRICATOR**  
 R.H. BOTTOM VERTICAL DRIVE  
 30:1 RATIO - 1 GALLON RESERVOIR  
 CONTAINS BUNA-N OIL SEALS



**Models 800309**  
**800561** SERIES  
**Series "B"**

34622 included with pumps,  
 slot covers and filler.



LUBRICATOR	HEATER ASSEMBLY	LOW LEVEL SWITCH ASSEMBLY
800309	—	—
800561	880065-1*	880174**

\* Refer to Section M6, Page 1 Series.  
 \*\* Refer to Section M30, Page 18 Series.

Drive Adaptation:  
 Refer to Section M3  
 Page 15 Series.


**SERVICE PARTS**

PART	QUAN.	DESCRIPTION
32090	2	Cover gasket end
32091-4	2	Cover gasket strip
34622	As req'd	Gasket
67007	1	Drain plug
69944	1	Strainer
360661	1	Cover plate
880019	1	Gauge glass assembly
880085	1	Filler assembly
880093	As req'd	Slot cover assembly
880187	As req'd	Model "55" pump assembly

**LINCOLN ST. LOUIS**  
 4010 GOODFELLOW BLVD • ST. LOUIS, MO. 63120 • (314) 383-5900



**SECTION - M2**  
**PAGE - 68A**



**RETAIN THIS INFORMATION FOR FUTURE REFERENCE**

When ordering replacement parts, list: Part Number, Description, Model Number, and Series Letter.  
 LINCOLN ST. LOUIS provides a Distributor Network that stocks equipment and replacement parts.