


Model No. 800019 Series LUBRICATOR Series "D"

L.H. END ROTARY DRIVE 1 GALLON RESERVOIR CONTAINS BUNA-N OIL SEALS

RATIO 800019 ----37.5:1



© Indicates Change

SERVICE PARTS

Part	Qty.	Description
32090	2	Cover gasket end
32091-4	2	Cover gasket strip
67007	2	Drain plug
68220	1	#3 Woodruff key
69944	1	Strainer
244429	1	Fluid level gauge
360661	1	Cover plate
880085	1	Filler assembly
880093	As req'd	Slot cover assembly
880130	2	Bracket assembly
880550	As req'd	Model "55i" pump assembly

NOTE: Part numbers listed on this page are correct, although drawing may not accurately illustrate production components.


Copyright 1994
Section - M2


A PENTAIR COMPANY

One Lincoln Way
St. Louis, Missouri 63120-1578
(314) 679-4200

Page - 40C

Mar - 94 FORM 402453





RETAIN THIS INFORMATION FOR FUTURE REFERENCE

When ordering replacement parts, list: Part Number, Description, Model Number, and Series Letter.

LINCOLN provides a Distributor Network that stocks equipment and replacement parts.